INTERNAL CARGO DAMAGE REPORT

AWB NO: 618-6333333



<u></u>		C	
General	l m	torma	tion
General			шоп

Reported By-----
Incident Date
Incident Time
Reporting station
2019-08-20
1:42 AM
AMS

Job Function

Airway Bill and Flight Information

AirlineMovementTransport TypeNumberSingapore Airlines Cargo------flight3563644

Master Airway BillDateAirport Of OriginAirport Of Destination618-63333332019-08-20Hyderabad-HDDKindersley Airport-YKY

Shipment Information

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

ididkd ------

Shipper Name MAWB Total Kilograms Actual Received Kilograms Issuing Agent

Damage Information

Exact Location

Method Of Packing Identification No Safety Threat Affected House AWB'S

---- Yes ------

Damage to Packing Content Affected Items Missing Condition Of Content

Tape loose Possibly Possibly ------

Suspected of Pilferage Affected Pcs Items Missing Pcs Affected Weight

Yes 45 67 ------

Items Missing Kg Recuperation Requried Recuperation Status Classification Type

Yes
-----Life Threat - Damage
involving safety of life or
property Inspection,
Decontamination and
verification is required.(e.g.
chemical, biological,
radioactive leakage or

spillage)

Investigation and Responsibility

Locaton Id

In AC compartment discoveredby gshsh ------

Internal Code Internal Responsibility Internal Area Area Supervisor

----- external ------

Cause Of Event

admin@cargoreport.aero 1

INTERNAL CARGO DAMAGE REPORT

AWB NO: 618-6333333



Upload Pictures and Documents

Damage Images

admin@cargoreport.aero 2