

**EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 035-95959869

**CARGO CLAIMS**

Loss prevention program

**General Information**

<b>Reported by</b> girish	<b>Reporting station</b> jhshss	<b>Incident Date</b> 2019-08-13	<b>Incident Time</b> 6:53 PM
------------------------------	------------------------------------	------------------------------------	---------------------------------

**Airway Bill and Flight Information**

<b>Airline</b> Aires Colombia (Aerovias de Integracion)	<b>Movement</b> -----	<b>Transport Type</b> flight	<b>Number</b> 9898998
<b>Master Airway Bill</b> 035-95959869	<b>Date</b> 2019-08-13	<b>Airport Of Origin</b> Hubli Airport-HBX	<b>Airport Of Destination</b> Juneau Airport-JNU

**Shipment Information**

<b>Content Nature</b> hdh	<b>MAWB Total Pieces</b> -----	<b>Actual Received Pieces</b> -----	<b>Consignee Name</b> -----
<b>Shipper Name</b> -----	<b>MAWB Total Kilograms</b> -----	<b>Actual Received Kilograms</b> -----	<b>Issuing Agent</b> -----

**Damage Information**

<b>Method Of Packing</b> -----	<b>Identification No</b> ndnd	<b>Safety Threat</b> yes	<b>Affected House AWB'S</b> -----
<b>Damage to Packing</b> Tape torn	<b>Content Affected</b> no	<b>Items Missing</b> -----	<b>Condition Of Content</b> -----
<b>Suspected of Pilferage</b> yes	<b>Affected Pcs</b> -----	<b>Items Missing PCS</b> -----	<b>Affected Weight</b> -----
<b>Recuperation Required</b> -----	<b>Recuperation Status</b> -----		

**Risk classification**

<b>Affected Weight</b> -----	<b>Calculated risk</b> [ Based on Montreal Convention 19 SDR per Kilogram ] -----
---------------------------------	--

**Classification Type**

Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)

Upload Pictures and Documents

**Damage Images**

-----

Damage Report