

INTERNAL CARGO DAMAGE REPORT

AWB NO: 009-3457776

CARGO CLAIMS

Loss prevention program

General Information

Reported By -----	Incident Date 2019-08-21	Incident Time 5:54 PM	Reporting station ZYA
-----------------------------	------------------------------------	---------------------------------	---------------------------------

Job Function

Warehouse Supervisor - 1

Airway Bill and Flight Information

Airline GMG Airlines	Movement -----	Transport Type flight	Number 555
Master Airway Bill 009-3457776	Date 2019-08-21	Airport Of Origin Amsterdam Airport Schiphol-AMS	Airport Of Destination Brussels National Airport-BRU

Shipment Information

Content Nature iwowowo	MAWB Total Pieces -----	Actual Received Pieces -----	Consignee Name -----
----------------------------------	-----------------------------------	--	--------------------------------

Shipper Name -----	MAWB Total Kilograms -----	Actual Received Kilograms -----	Issuing Agent -----
------------------------------	--------------------------------------	---	-------------------------------

Damage Information

Method Of Packing -----	Identification No -----	Safety Threat No	Affected House AWB'S -----
-----------------------------------	-----------------------------------	----------------------------	--------------------------------------

Damage to Packing Damp	Content Affected No	Items Missing -----	Condition Of Content -----
----------------------------------	-------------------------------	-------------------------------	--------------------------------------

Suspected of Pilferage No	Affected Pcs -----	Items Missing Pcs -----	Affected Weight -----
-------------------------------------	------------------------------	-----------------------------------	---------------------------------

Items Missing Kg -----	Recuperation Required -----	Recuperation Status -----	Classification Type Minor - Small tears, dents or scratches to the outer packaging only
----------------------------------	---------------------------------------	-------------------------------------	---

Investigation and Responsibility

Damage Discovered In AC compartment	Discovers By Caused discoveredby	Internal Name ooweowow	Internal Group -----
---	--	----------------------------------	--------------------------------

Internal Code -----	Internal Responsibility external	Internal Area -----	Area Supervisor -----
-------------------------------	--	-------------------------------	---------------------------------

Exact Location -----	Locaton Id -----	Cause Of Event -----
--------------------------------	----------------------------	--------------------------------

Upload Pictures and Documents

Damage Images

Damage Report