## **INTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-49648845



## **General Information**

Reported ByIncident DateIncident TimeReporting stationVasanthi2019-08-134:02 PMAMS

**Job Function** 

-----

**Airway Bill and Flight Information** 

AirlineMovementTransport TypeNumberGMG Airlinesoutboundflight7597568846688

Master Airway BillDateAirport Of OriginAirport Of Destination009-496488452019-08-13Amsterdam Airport Schiphol-<br/>AMSBrussels National Airport-BRU

**Shipment Information** 

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

Dhv ------

Shipper Name MAWB Total Kilograms Actual Received Kilograms Issuing Agent

-----

**Damage Information** 

Method Of Packing Identification No Safety Threat Affected House AWB'S

---- yes -----

Damage to Packing Content Affected Items Missing Condition Of Content

Crushed no no Overheated

Suspected of Pilferage Affected Pcs Items Missing Pcs Affected Weight

yes ------ ------

Items Missing Kg Recuperation Requried Recuperation Status Classification Type

yes Package strapped Life Threat - Damage involving safety of life or property Inspection,
Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or

spillage)

Investigation and Responsibility

Damage Discovered Discoveres By Caused Internal Name Internal Group

----- discoveredby Dbvfg ------

Internal Code Internal Responsibility Internal Area Area Supervisor

internal code internal responsibility internal Area Supervisor

Exact Location Locaton Id Cause Of Event

admin@cargoreport.aero 1

## **INTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-49648845



**Upload Pictures and Documents** 

Damage Images

-----

admin@cargoreport.aero 2