INTERNAL CARGO DAMAGE REPORT

AWB NO: 009-5555555



<u></u>		C	
General	l m	torma	tion
General			шоп

Incident Date Incident Time Reporting station Reported By

2019-08-21 4:46 PM ZYA

Job Function

Airway Bill and Flight Information

Airline **Transport Type** Number Movement **GMG** Airlines 25888888 flight

Master Airway Bill Airport Of Origin Airport Of Destination Date

009-555555 2019-08-21 Amsterdam Airport Schiphol- Brussels National Airport-BRU

AMS

Shipment Information

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

ggjmbv

Shipper Name MAWB Total Kilograms Actual Received Kilograms Issuing Agent

Damage Information

Method Of Packing Identification No Safety Threat Affected House AWB'S

No

Damage to Packing Content Affected Items Missing Condition Of Content

Tape loose

Suspected of Pilferage Affected Pcs **Items Missing Pcs Affected Weight**

Items Missing Kg Recuperation Requried Recuperation Status Classification Type

Minor - Small tears, dents or scratches to the outer

packaging only

Investigation and Responsibility

Discoveres By Caused Internal Name Damage Discovered Internal Group

discoveredby bxjxxh

Internal Code Internal Responsibility Internal Area Area Supervisor

external

Exact Location Locaton Id **Cause Of Event**

1 admin@cargoreport.aero

AWB NO: 009-555555



Upload Pictures and Documents

Damage Images





admin@cargoreport.aero 2