INTERNAL CARGO DAMAGE REPORT

AWB NO: 009-666677



Loss prevention program

| General Information | | | |
|---|---|--|---|
| Reported By | Incident Date 2019-08-21 | Incident Time 6:15 PM | Reporting station AMS |
| Job Function Warehouse Supervisor - 1 | | | |
| Airway Bill and Flight Information | | | |
| Airline GMG Airlines | Movement | Transport Type flight | Number 55677 |
| Master Airway Bill 009-666677 | Date 2019-08-21 | Airport Of Origin Amsterdam Airport Schiphol- AMS | Airport Of Destination Brunei International Airport- BWN |
| Shipment Information | | | |
| Content Nature fghjk | MAWB Total Pieces | Actual Received Pieces | Consignee Name |
| Shipper Name | MAWB Total Kilograms | Actual Received Kilograms | Issuing Agent |
| Damage Information | | | |
| Method Of Packing | Identification No | Safety Threat No | Affected House AWB'S |
| Damage to Packing Tip and tell indicator | Content Affected No | Items Missing | Condition Of Content |
| Suspected of Pilferage No | Affected Pcs | Items Missing Pcs | Affected Weight |
| Items Missing Kg | Recuperation Requried | Recuperation Status | Classification Type Minor - Small tears, dents or scratches to the outer packaging only |
| Investigation and Respon | sibility | | |
| Damage Discovered During build-up | Discoveres By Caused discoveredby | Internal Name fgh | Internal Group |
| Internal Code | Internal Responsibility external | Internal Area | Area Supervisor |
| Exact Location | Locaton Id | Cause Of Event | |

AWB NO: 009-666677



Loss prevention program

Upload Pictures and Documents

Damage Images
