INTERNAL CARGO DAMAGE REPORT

AWB NO: 009-98979797



General Information

Reported By Incident Date Incident Time Reporting station

------ 2019-08-19 4:15 PM ZYA

Job Function

Airway Bill and Flight Information

AirlineMovementTransport TypeNumberGMG Airlines------flight7997979

Master Airway BillDateAirport Of OriginAirport Of Destination009-989797972019-08-19Amsterdam Airport Schiphol-Brussels National Airport-BRU

AMS

Shipment Information

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

jdn -------

Shipper Name MAWB Total Kilograms Actual Received Kilograms Issuing Agent

Damage Information

Method Of Packing Identification No Safety Threat Affected House AWB'S

ULD ------ no ------

Damage to Packing Content Affected Items Missing Condition Of Content

Crushed no ------

Suspected of Pilferage Affected Pcs Items Missing Pcs Affected Weight

no ------ ------

Items Missing Kg Recuperation Requried Recuperation Status Classification Type

------ Minor

Investigation and Responsibility

Damage Discovered Discoveres By Caused Internal Name Internal Group

During build-up discoveredby hxhx ------

Internal Code Internal Responsibility Internal Area Area Supervisor

------ external ------

Exact Location Locaton Id Cause Of Event

admin@cargoreport.aero 1

INTERNAL CARGO DAMAGE REPORT

AWB NO: 009-98979797



Upload Pictures and Documents

Damage Images

admin@cargoreport.aero 2