

INTERNAL CARGO DAMAGE REPORT

AWB NO: 020-49494949

CARGO CLAIMS

Loss prevention program

General Information

Reported By girish	Incident Date 2019-08-13	Incident Time 6:18 PM	Reporting station ZYA
------------------------------	------------------------------------	---------------------------------	---------------------------------

Job Function

Airway Bill and Flight Information

Airline Lufthansa Cargo	Movement -----	Transport Type flight	Number 679799779
Master Airway Bill 020-49494949	Date 2019-08-13	Airport Of Origin Hyderabad-HDD	Airport Of Destination London Rail Station-XDQ

Shipment Information

Content Nature jdndn	MAWB Total Pieces 25	Actual Received Pieces 36	Consignee Name -----
--------------------------------	--------------------------------	-------------------------------------	--------------------------------

Shipper Name -----	MAWB Total Kilograms -----	Actual Received Kilograms -----	Issuing Agent -----
------------------------------	--------------------------------------	---	-------------------------------

Damage Information

Method Of Packing -----	Identification No bbnn	Safety Threat yes	Affected House AWB'S -----
-----------------------------------	----------------------------------	-----------------------------	--------------------------------------

Damage to Packing Tape loose,djj	Content Affected no	Items Missing no	Condition Of Content -----
--	-------------------------------	----------------------------	--------------------------------------

Suspected of Pilferage yes	Affected Pcs -----	Items Missing Pcs -----	Affected Weight -----
--------------------------------------	------------------------------	-----------------------------------	---------------------------------

Items Missing Kg -----	Recuperation Required -----	Recuperation Status -----	Classification Type Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)
----------------------------------	---------------------------------------	-------------------------------------	---

Investigation and Responsibility

Damage Discovered In AC compartment	Discovers By Caused causedby	Internal Name hxhxx	Internal Group -----
---	--	-------------------------------	--------------------------------

Internal Code -----	Internal Responsibility external	Internal Area -----	Area Supervisor -----
-------------------------------	--	-------------------------------	---------------------------------

Exact Location -----	Locaton Id -----	Cause Of Event -----
--------------------------------	----------------------------	--------------------------------

Upload Pictures and Documents

Damage Images

