INTERNAL CARGO DAMAGE REPORT

AWB NO: 074-72727



General Information

Incident Date Incident Time Reporting station Reported By

2019-08-20 4:41 PM OAX

Job Function

Airway Bill and Flight Information

Airline Transport Type Number Movement 123131 KLM Cargo flight -----

Master Airway Bill Airport Of Origin Airport Of Destination Date 074-72727 2019-08-20 Amsterdam Airport Schiphol- Qaqortoq Airport-JJU

AMS

Shipment Information

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

hdjsj

Shipper Name MAWB Total Kilograms Actual Received Kilograms Issuing Agent

Damage Information

Method Of Packing Identification No Safety Threat Affected House AWB'S

No

Condition Of Content Damage to Packing Content Affected Items Missing

Tape torn Dented

Suspected of Pilferage Affected Pcs **Items Missing Pcs Affected Weight**

Items Missing Kg Recuperation Requried Recuperation Status Classification Type

Minor - Small tears, dents or scratches to the outer

packaging only

Investigation and Responsibility

Damage Discovered Discoveres By Caused Internal Name Internal Group

In AC compartment discoveredby dbnx

Internal Code Internal Responsibility Internal Area Area Supervisor

external

Exact Location Locaton Id **Cause Of Event**

1 admin@cargoreport.aero


AWB NO: 074-72727



Upload Pictures and Documents

Damage Images





admin@cargoreport.aero 2