## **EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-68989898



General Information										
Reported by	<b>Reporting station</b> OAX	Incident Date 2019-08-20	Incident Time 6:40 PM							
Airway Bill and Flight Information										
<b>Airline</b> GMG Airlines	Movement	<b>Transport Type</b> flight	<b>Number</b> 866898989							
Master Airway Bill 009-68989898	<b>Date</b> 2019-08-20	<b>Airport Of Origin</b> Amsterdam Airport Schiphol- AMS	<b>Airport Of Destination</b> Brussels National Airport-BRU							
<b>Shipment Information</b>										
Content Nature hxhx	MAWB Total Pieces	Actual Received Pieces	Consignee Name							
Shipper Name	MAWB Total Kilograms	Actual Received Kilograms	Issuing Agent							
Damage Information			$\mathcal{Y}$							
Method Of Packing	Identification No	<b>Safety Threat</b> Yes	Affected House AWB'S							
<b>Damage to Packing</b> Broken	<b>Content Affected</b> Yes	Items Missing	<b>Condition Of Content</b> Crushed							
Suspected of Pilferage Yes	Affected Pcs 25	Items Missing PCS	Affected Weight							
Recuperation Requried	Recuperation Status									

D	ie	10	155	16	 ŧi،	n m

Affected Weight Calculated risk [ Based on Montreal Convention 19 SDR per Kilogram ]

\_\_\_\_\_

**Classification Type** 

Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)

admin@cargoreport.aero

## **EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-68989898



**Upload Pictures and Documents** 

Damage Images

-----

admin@cargoreport.aero 2