## **EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-86595657



l Information

Reported byReporting stationIncident DateIncident TimeVasanthiAMS2019-08-195:45 PM

**Airway Bill and Flight Information** 

AirlineMovementTransport TypeNumberGMG Airlines-------flight756899258

Master Airway BillDateAirport Of OriginAirport Of Destination009-865956572019-08-19Brussels National Airport-BRU Hyderabad-HDD

**Shipment Information** 

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

Content ------ ------

Shipper Name MAWB Total Kilograms Actual Received Kilograms Issuing Agent

----

**Damage Information** 

Method Of Packing Identification No Safety Threat Affected House AWB'S

------ No ------

Damage to Packing Content Affected Items Missing Condition Of Content

Crushed No ------

Suspected of Pilferage Affected Pcs Items Missing PCS Affected Weight

NO ------ ------ ------

Recuperation Requried Recuperation Status

Risk classification

Affected Weight Calculated risk [ Based on Montreal Convention 19 SDR per Kilogram ]

-----

**Classification Type** 

Minor - Small tears, dents or scratches to the outer packaging only

admin@cargoreport.aero 1

## **EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-86595657



**Upload Pictures and Documents** 

Damage Images

\_\_\_\_\_

admin@cargoreport.aero 2