## **EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-8888888



General Information						
Reported by	<b>Reporting station</b> ZYA	Incident Date 2019-08-21	Incident Time 4:52 PM			
Airway Bill and Flight Information						
<b>Airline</b> GMG Airlines	Movement 	<b>Transport Type</b> flight	<b>Number</b> 5566585			
Master Airway Bill 009-8888888	<b>Date</b> 2019-08-21	<b>Airport Of Origin</b> Amsterdam Airport Schiphol- AMS	<b>Airport Of Destination</b> Brussels National Airport-BRU			
Shipment Information						
<b>Content Nature</b> ggghh	MAWB Total Pieces	Actual Received Pieces	Consignee Name			
Shipper Name	MAWB Total Kilograms	Actual Received Kilograms	Issuing Agent 			
Damage Information						
Method Of Packing	Identification No	<b>Safety Threat</b> No	Affected House AWB'S			
<b>Damage to Packing</b> Crushed	<b>Content Affected</b> No	Items Missing	Condition Of Content			
<b>Suspected of Pilferage</b> No	Affected Pcs	Items Missing PCS	Affected Weight			

Ris	C C	assi	fica	tion

**Recuperation Requried** 

Affected Weight Calculated risk [ Based on Montreal Convention 19 SDR per Kilogram ]

----

**Classification Type** 

**Recuperation Status** 

Minor


admin@cargoreport.aero

AWB NO: 009-8888888



## **Upload Pictures and Documents**

## Damage Images



admin@cargoreport.aero 2