EXTERNAL CARGO DAMAGE REPORT

AWB NO: 009-95994



General Information					
Reported by girish	Reporting station ZYA	Incident Date 2019-08-19	Incident Time 1:02 PM		
Airway Bill and Flight Info	rmation				
Airline GMG Airlines	Movement 	Transport Type flight	Number 89886		
Master Airway Bill 009-95994	Date 2019-08-19	Airport Of Origin Amsterdam Airport Schiphol- AMS	Airport Of Destination Brussels National Airport-BRU		
Shipment Information					
Content Nature gshe	MAWB Total Pieces	Actual Received Pieces	Consignee Name		
Shipper Name 	MAWB Total Kilograms	Actual Received Kilograms	Issuing Agent		
Damage Information			\mathcal{Y}		
Method Of Packing	Identification No	Safety Threat yes	Affected House AWB'S		
Damage to Packing Seal open,Packing missing	Content Affected yes	Items Missing	Condition Of Content Sick		
Suspected of Pilferage yes	Affected Pcs 25	Items Missing PCS	Affected Weight		
Recuperation Requried	Recuperation Status				

-	пч	~	_	SS	6 - 1			~ "	١.
	11-1	ч.	L÷.	1		ча	41	w.	

Affected Weight Calculated risk [B	Based on Montreal Convention 19 SDR per Kilogram]
-------------------------------------	--

Classification Type

Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)

admin@cargoreport.aero

EXTERNAL CARGO DAMAGE REPORT

AWB NO: 009-95994



Upload Pictures and Documents

Damage Images

admin@cargoreport.aero 2