## **EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 774-12356980



General Information			
<b>Reported by</b> Nageswar	<b>Reporting station</b> BRU	Incident Date 2019-08-23	Incident Time 6:50 PM
Airway Bill and Flight Info	ormation		
<b>Airline</b> Shanghai Airlines	<b>Movement</b> inbound	<b>Transport Type</b> flight	Number 23
<b>Master Airway Bill</b> 774-12356980	<b>Date</b> 2019-08-23	<b>Airport Of Origin</b> Rajiv Gandhi International Airport-HYD	<b>Airport Of Destination</b> Vijayawada Airport-VGA
Shipment Information			7(°)\\)
<b>Content Nature</b> glasses	MAWB Total Pieces	Actual Received Pieces	Consignee Name
Shipper Name	MAWB Total Kilograms	Actual Received Kilograms	Issuing Agent
Damage Information			9
<b>Method Of Packing</b> Carton box	<b>Identification No</b> tyuijhg	Safety Threat No	Affected House AWB'S
<b>Damage to Packing</b> Dented,Broken	<b>Content Affected</b> No	<b>Items Missing</b> No	Condition Of Content Overheated,Sick
<b>Suspected of Pilferage</b> No	Affected Pcs	Items Missing PCS	Affected Weight
<b>Recuperation Requried</b> No	Recuperation Status		

Dicke	lassification	

Affected Weight Calculated risk [ Based on Montreal Convention 19 SDR per Kilogram ]

-----

**Classification Type** 

Minor - Small tears, dents or scratches to the outer packaging only

admin@cargoreport.aero

## **EXTERNAL CARGO DAMAGE REPORT**

AWB NO: 774-12356980



**Upload Pictures and Documents** 

Damage Images

-----

admin@cargoreport.aero 2